Thank you for your purchase. In order to program the Code CR900/CR921 barcode scanners to work with AIMsi v10, users may have to scan the sequence of programming commands listed below. These commands add a carriage return to the end of 1D barcode scans to advance the cursor to the next field position within AIMsi. The other settings program the device's 2D driver license output to match the AIMsi format. Please scan all four codes in the order listed.

AIMsi v10

Reset to USB Factory Defaults M10002_02 E2	Resets the device to factory defaults including suffix enter after 1D code scans
PDF417 On M10070_01 D4	Enables default driver license scanning options

Keyboard Control Characters for Non Printable ASCII M10412_01 A4	Sets formatting of driver license output to be compatible with AIMsi v10
Reboot Reader M10296_01 C4	Reboots the scanner to apply changes – the device will take a minute to shut down & then power back on. Please wait until the device is finished restarting before scanning new items